



The official factory source for all  
Verteq products and services.

Marteq Process Solutions, Inc.  
1721 S. Grand Avenue  
Santa Ana, CA 92705-4808  
PH: 714-495-4275 FX: 714-495-4289  
[www.marteqpro.com](http://www.marteqpro.com)

### SuperClean 1800-6 Rinser/Dryer Spare Parts List

Part#	Description	Qty	Critical Spares Qty	Consumable Spares Qty	Can be Repaired
1062563.1	Hub	1			Yes
1067786.5	Encl assy resist monitor hard	1	1		Yes
1067803.1	Probe,resistivity & cable assy	1			
1069144.3	Screw 316SS Socket Nedox Coat	4		4	
1070125.1	Seal,static	2			
1070237.7	Seal Door 1800 EPDM	1		1	
1070267.1	Auto positioner cyl assy 1800	1	1		
1071522.1	Seal Plate Labyrinth	1			
1072583.1	Switch A,door CYL1800	1			
1072587.1	Gasket manifold 1800 Ar Al Ad	1			
1072597.1	Valve Assy Safety 1800	1			
1072598.1	Manifold Assy 1800-6H	1			
1072603.1	STATIC ELIM PWR SOURCE ASSY	1			
1075227.xxx	Controller,1800-6 ( <i>advise style standard?</i> )	1	1		Yes
1081890.5	Keypad 1800/SC200-300/8201 STD	1	1		Yes
1085566.1	OVERSPEED BOARD	1	1		Yes
4117955	Filter,12stk phobic,gas	1		1	
4118312	Thermostat	2			
4118898	Elbow,barb polypro 1/8px1/8id	1		1	
4119386	Heater,nitrogen 2490	1			
4119414	Switch,pressure 5psi	1			
4119415	Damper,vibration 70lb	4		4	
4119421	Valve, Sol 120 VAC	3	3		
4119437	Regulator,Pressw/0-100psi Gage	1			
4119576	Switch,press 45psi	1			
4119644	Relay,pc mount 120vac coil	3			
4119723	Valve,8port manifold D1/N2,pvc	1			
4119839	Controller,speed control	1	1		
4120061	Valve,Check Flow Control	2			
4120066	Cylinder,air,2" Bx5",str	1			
4120356	Elbow,1/8px1/16 barb,nylon	1		1	
4128051	Valve,Pne,PFA,2 Way,1/4",NC	1			
1800-6 rotors	ROTOR	1	1		Yes
rotor rods	rotor rod kits (Teflon sheaths of PFA rods depend on Rotor part number and rotor type)	1 ea = pair	1	1	

#### About Rotors and hubs

The rotor part number is stamped on the actual rotor.

**Rotor repairs/refurb includes:** balance and electropolish as well as checking for carrier fit, bent bars and oversized hub holes.

**Hub repair/refurb includes:** balance and electropolish as well as checking for stripped screws.

**Note:** Some speciality rotors may require a sample load with cassette for balancing purposes. Check with Marteq at time of order.

#### Leadtimes

**New buy Spares:** Worst case leadtimes are 6-8 weeks if quantity in stock is 0 at time of order placement.

**Repair/Refurb:** Leadtimes are estimated a 4-6 weeks.

For pricing and availability please contact:

[parts@marteqpro.com](mailto:parts@marteqpro.com)