



The official factory source for all Verteq products and services.

Marteq Process Solutions, Inc.
 1721 S. Grand Avenue
 Santa Ana, CA 92705-4808
 PH: 714-495-4275 FX: 714-495-4289
www.marteqpro.com

SuperClean 1600-55A Spare Parts List

Part#	Description	Qty Req'd	Critical Spares Qty	Consumable Spares Qty	Can be Repaired
1059696.1	Gasket,static elim.	1			
1062531.1	Seal,gasket di	1			
1062546.1	Seal,Labyrinth Plate	1			
1062563.1	HUB	1	1		Yes
1062608.1	Key,motor	1			
1062608.3	Key,Motor	1			
1064788.1	Seal,Rect,Door,1600	1		1	
1064827.1	Heater,blanket 5.00X5.00	2			
1064832.3	Heater,strip 1x36	1			
1065681.1	Gasket,N2	1			
1067786.5	Encl assy resist monitor hard	1	1		Yes
1067803.1	Probe,resistivity & cable assy	1			
1067811.1	PCB Assy,optical sensor	1			
1067878.1	Gasket,drain box	1			
1069144.3	Screw 316SS Socket Nedox Coat	4		4	
1069254.501	Static Eliminator Assy	1			
1070206.x	Valve Assy Spares DI <i>(advise style LP or HP)</i>	1			
1074599.x	1600-55A&M bowl <i>(RA63 or RA10 finish)</i>	1			Yes
1075227.xxx	CONTROLLER,1600-55 <i>(advise style standard?)</i>	1	1		Yes
1081890.1	Keypad 1600.55 STD	1	1		Yes
1104606.1.8	MOTOR, 1600 MOTOR (was P/N 4129167)	1			
4114217	Switch,lens,red	1			
4114218	Switch,lens,grn 4899	1			
4114219	Lens,yellow	1			
4114316	Ring,o,epdm	1			
4114320	Switch,lens 4898	1			
4114327	Switch,pressure	1			
4115243	Relay,2 pole,20 amp	1			
4115688	FILTER N2 WAFERGD CARTRIDGE	1		1	
4115770	Ring-o,"Viton"	1			
4115771	Ring,o,epdm,viton	1			
4115777	Actuator,switch,sleeve,mom	1			
4115778	Actuator,sleeve maintained	1			
4115779	Switch,mtg flange	1			
4115781	Switch,contact block	1			
4115782	Switch,contact blk	1			
4115848	Switch,mini per 10 63084-1	1			
4116362	Thermostat 4131	1			
4116634	Shock	2			
4116635	Shock	6			
4116783	Switch,boot 4897	1			
4117376	Thermostat,setpoint 70d	1			
4117725	Varistor,150 vac	1			
4117876	Nozzle,Tfe Spray Veejet	6			
4118199	Filter,inline gas (1/4"npt)	1	1		
4118312	Thermostat	1			
4118741	Snubber,RC,100OHM,.1UF600V	1			
4119822	Switch,door cylinder	1			
4120866	Ring,o viton .208idx.07w	1			
1600 rotors	ROTOR	1	1		yes
rotor rods	rotor rod kits (Teflon sheaths of PFA rods depend on Rotor part number and rotor type)	1 ea = pair	1	1	

About Rotors and hubs

The rotor part number is stamped on the actual rotor.

Rotor repairs/refurb includes: balance and electropolish as well as checking for carrier fit, bent bars and oversized hub holes.

Hub repair/refurb includes: balance and electropolish as well as checking for stripped screws.

Note: Some speciality rotors may require a sample load with cassette for balancing purposes. Check with Marteq at time of order.

Leadtimes

New buy Spares: Worst case leadtimes are 6-8 weeks if quantity in stock is 0 at time of order placement.

Repair/Refurb: Leadtimes are estimated a 4-6 weeks.

For pricing and availability please contact:

parts@marteqpro.com